



<b>Site Name:</b>	Prospect Tower
<b>Structure Type:</b>	Guyed Tower
<b>Structure Height:</b>	220'
<b>Make:</b>	Rohn
<b>Model:</b>	80
<b>Tower Owner:</b>	Government of Bermuda
<b>Address:</b>	Fort Hill Road
<b>Parish:</b>	Devonshire
<b>Latitude:</b>	32.299186
<b>Longitude:</b>	-64.765877
<b>Date of Visit:</b>	6/3/2019
<b>Employees on Site:</b>	Angie Shyrigh
	Ben Shyrigh
	Brian Heiney

**Proventus Structural Services, LLC**

Please contact Angie Shyrigh with any questions regarding the content of this report.  
(614)312-8107

# Table of Contents

Table of Contents.....	2
Purpose of this Site Visit.....	3
General Information.....	3
Access and Compound.....	4
Concrete Foundations.....	5
Structure Condition.....	6
Finish.....	7
Lighting.....	8
Grounding.....	9
Personnel Safety.....	10
Antennas and Lines.....	11
Coax Position Diagram.....	11
Loading.....	12
Guy Wires and Associated Hardware.....	14
Guy Anchor and Guy Wire Position Codes.....	15
Guy Tension Results.....	16
Tower Alignment.....	18
Photos.....	19

**Proventus Structural Services, LLC**

*Please contact Angie Shyrigh with any questions regarding the content of this report.  
(614)312-8107*

## **Purpose of this Site Visit**

To fulfill the inspection requirements set forth in the TIA/EIA222-G, Annex J.1 standard for Maintenance and Condition Assessment of communication structures.

## **General Information**

If a manufacturer's plate is installed, record the information here:

A manufacturer's plate is not installed; however, the design details are congruent with Rohn model 80 tower.

### **Elevations**

Ground to top of pier pad: 2"

Top of pier pad to top of base plate: 1"

Top of base plate to top of structure: 220'

Tip height of highest appurtenance: 230'

What is the highest appurtenance? Omni antenna

### **Leg Orientation**

Legs are labeled in a clockwise fashion with "A leg" as the northernmost leg.

Azimuth of "A leg": 315°

*Note: while recommendations for corrective actions regarding tower mounted equipment and the guying system are provided in this report, due to the quantity of irreparably rust-damaged members, the strongest recommendation is the tower be decommissioned at the earliest possible date.*

## **Proventus Structural Services, LLC**

*Please contact Angie Shyrigh with any questions regarding the content of this report.  
(614)312-8107*

## **Access and Compound**

- Access road
- Compound gates & fencing
- Compound substrate
- Shelter exteriors

## **Observations**

The access and compound are in fair condition with no deficiencies observed.

**Proventus Structural Services, LLC**

*Please contact Angie Shyrigh with any questions regarding the content of this report.  
(614)312-8107*

## Concrete Foundations

- Ground condition
  - Settlement, movement, earth cracks
  - Erosion
  - Site condition (standing water, drainage, trees, etc.)
- Anchorage condition
  - Nuts and/or locking device (tightened)
  - Grout condition
  - Anchorage and/or anchor rod condition
- Concrete condition
  - Cracking, spalling, or splitting
  - Chipped or broken concrete
  - Honeycombing
  - Low spots to collect moisture

### Observations

The tower foundation is in fair, functional condition with no deficiencies observed.

**Proventus Structural Services, LLC**

*Please contact Angie Shyrigh with any questions regarding the content of this report.  
(614)312-8107*

## Structure Condition

- Damaged members (legs and bracing)
- Loose members
- Missing members
- Climbing facilities, platforms, catwalks – all secure
- Loose and/or missing bolts and/or locking devices
- Visible cracks in welded connections

## Observations

Elevation	Location	Description	Recommendation	Priority
70' 6", 205'	Varies	Locking hardware is not installed on the torque arm connection bolt assemblies.	Install locking hardware on the bolt assemblies. (24) 5/8" Ø PAL nuts are required to correct.	To be scheduled within 12 months

### Proventus Structural Services, LLC

Please contact Angie Shyrigh with any questions regarding the content of this report.  
(614)312-8107

## Finish

- Paint and/or galvanizing condition
- Rust and/or corrosion condition including mounts and accessories
- FAA or ICAO color marking conditions
- Water collection in members (to be remedied, e. g. unplug drain holes, etc.)

### **Note: Corrosion Definitions**

*Category 1 rust: light discoloration of steel surface, galvanizing may be wearing thin however rust does not penetrate steel and there is no loss of material. Recommended action is generally to monitor and record condition to determine the advancement of the condition.*

*Category 2 rust: discoloration is heavy and light pitting may be present. Recommended action is generally to brush region and treat with zinc rich compound. After treatment, region should be monitored and condition recorded at regular intervals to determine advancement of condition.*

*Category 3 rust: heavy pitting, flaking and/or loss of material is present. Recommended action is generally to replace component. If component replacement is not feasible, a review of condition by a professional engineer is recommended to determine course of action.*

### **Observations**

Extreme and extensive rust related material loss was observed on the bracing members of the tower. Bracing members are tubular, pinched at each end to create a ply that may be drawn into firm contact with the gusset once bolted. Despite the presence of a weep hole at each pinched end, these members are prone to holding water, rusting and “blowing out”. The lowest “blow out” was observed at the 5’ elevation. The quantity of members with this condition increases at higher elevations with approximately 40% of the members “blown out” at 80’.

Following are areas of special concern:

- Scaling rust is present at the C Leg weld to the base plate. This region of rust has advanced rapidly since the 2017 inspection
- Antenna #9 is a 4’ microwave dish mounted to a 4’ long antenna mount. It has a stiff arm which is connected to a diagonal member. This member is rusted though at its lower connection with only an estimated 50% of original material remaining.

Each of these members presents a serious drop hazard which may then contribute to the failure of the structure.

Due to the location of this tower at a manned facility with cars, human & vehicular traffic all within the drop/fall radius of this tower, it should be considered imperative to completely remove the structure as soon as possible. In its current condition, the tower poses a significant hazard to property and life.

### **Proventus Structural Services, LLC**

*Please contact Angie Shyrigh with any questions regarding the content of this report.  
(614)312-8107*

## Lighting

- Conduit, junction boxes and fasteners (weather tight and secure)
- Drain and vent openings (unobstructed)
- Wiring condition
- Light lenses
- Photo cell facing north
- Bulb condition
- Controller function if accessible

Light Type	Elevation	Location
LED Sidelight	109'	A Leg
LED Sidelight	109'	B Leg
LED Sidelight	109'	C Leg
Dual Strobe	219'	C Leg
LED Sidelight	109'	A Leg

## Observations

Elevation	Location	Description	Recommendation	Priority
109'	B Leg	The side light has no closure clips and is secured with a hose clamp.	It is recommended that replacement hose clamps from the manufacturer be installed.	To be scheduled

### Proventus Structural Services, LLC

Please contact Angie Shyrigh with any questions regarding the content of this report.  
(614)312-8107



## Grounding

- Connections
- Corrosion
- Lightning protection (secured to structure)

## Observations

Elevation	Location	Description	Recommendation	Priority
220'	Tower top	A lightning rod is installed at the top of the tower however the highest appurtenance is a 20' omni.	It is recommended an extension be installed for the lightning rod and the omni antenna elevation be lowered with the result that the tip of the lightning rod is at least 1' higher than the tip of the omni antenna.	To be scheduled

### Proventus Structural Services, LLC

Please contact Angie Shyrigh with any questions regarding the content of this report.  
(614)312-8107

## Personnel Safety

- Presence and condition of safety cable system
- Integrity of climbing facilities
- Availability of adequate anchorage points throughout height of climb

## Observations and Issues Found

Elevation	Location	Description	Recommendation	Priority
Throughout height	C Leg	Category 3 rust is present on the safety cable.	It is recommended the safety cable system be replaced and that the safety cable kit be installed per manufacturer's specifications.	To be scheduled within 12 months


### Proventus Structural Services, LLC

Please contact Angie Shyrigh with any questions regarding the content of this report.  
(614)312-8107

## Antennas and Lines

- Antenna condition
- Mount and/or ice shield condition (bent, loose, and/or missing members)
- Feedline condition (flanges, seals, dents, jacket damage, grounding, etc.)
- Feedline hanger condition (snap-ins, bolt on, kellum grips, etc.)
- Secured to structure

## Coax Position Diagram



### Proventus Structural Services, LLC

Please contact Angie Shyrigh with any questions regarding the content of this report.  
(614)312-8107

# Loading

#	Elev.	Location	Az.	Antennas			External Devices				Feedlines				Mounts				
				Make	Model	Description	Quant.	Make	Model	Description	Quant.	Size	In/Out	Coax Position*	Elev.	Description	Height	Width	Offset
1	24'	A LEG	N/A	ILLEGIBLE	ILLEGIBLE	20' DIPOLE	NONE				1	7/8"	OUTSIDE	F2	24'	STANDOFF	1' 6"	2"	1'
2	46'	A LEG	235°	ANATEL	MINI-LINK ANTO9.6HP	3' DISH	1	ERICSSON	RAU2 X 6U/A31	ODU	1	1/4"	OUTSIDE	A LEG	46'	CLAMPSET TO LEG	N/A	N/A	N/A
3	46'	B LEG	350°	ILLEGIBLE	ILLEGIBLE	1' SQUARE PANEL	NONE				1	CAT5	INSIDE	F7	46'	CLAMPSET TO LEG	N/A	N/A	N/A
4	48'	C LEG	N/A	COMMSCOPE	DB224-B	20' DIPOLE	NONE				1	7/8"	INSIDE	F8	48'	STANDOFF	1' 6"	2"	1'
5	48' 6"	B LEG	50°	ANATEL	MINI-LINK ANTO9.6HP	3' DISH	1	ERICSSON	RAU2 X 6U/A31	ODU	1	1/4"	OUTSIDE	A LEG	48' 6"	CLAMPSET TO LEG	N/A	N/A	N/A
6	50'	A LEG	235°	ERICSSON	ANT2 0.6 13 HP	2' DISH	NONE				1	1/2"	OUTSIDE	F9	52'	PIPE MOUNT	5'	4"	1'
7	53'	A LEG	50°	ERICSSON	ANT2 0.6 13 HP	2' DISH	NONE				1	1/2"	OUTSIDE	F9					
8	58'	A LEG	235°	COMMSCOPE	VHLP4-6W-DW1C	4' DISH	2	DRAGONWAVE	RLHP15B1	ODU	2	3/8"	INSIDE	F6	58'	STANDOFF	4"	3-1/2"	4'
9	58'	B LEG	50°	COMMSCOPE	VHLP4-6W-DW1C	4' DISH	2	DRAGONWAVE	RLHP15B1	ODU	2	3/8"	INSIDE	F6	58'	STANDOFF	4"	3-1/2"	4'
10	63'	A LEG	315°	COMMSCOPE	VHLP3-6W-DW1	3' DISH	2	DRAGONWAVE	RLHP15B1	ODU	2	3/8"	INSIDE	F6	58'	STANDOFF	4"	3-1/2"	4'
11	63'	B LEG	50°	COMMSCOPE	VHLP4-6W-DW1C	4' DISH	2	DRAGONWAVE	RLHP15B1	ODU	2	3/8"	INSIDE	F6	58'	STANDOFF	4"	3-1/2"	4'
12	71'	A LEG	235°	RADIOWAVES	HPCPE-23DW2	1' DISH	1	DRAGONWAVE	PHHP23B3SXR1	ODU	1	3/8"	INSIDE	F6	71'	STANDOFF	5'	2-1/2"	1' 6"
13	73'	B LEG	50°	COBHAM	AFS-DBG-0360-01	2' PANEL	1	REDLINE	RDL-3000	ODU	1	3/8"	INSIDE	F6	73'	STANDOFF	3'	2 3/8"	1' 6"
14	76'	B LEG	195°	RADIOWAVES	ILLEGIBLE	2' DISH	1	REDLINE	RDL-3000	ODU	1	3/8"	INSIDE	F6			6'	2 3/8"	1' 6"
15	78'	AB FACE	N/A	NONE			NONE				3	7/8" 1/2"	INSIDE	AB FACE	NONE				
16	76'	A LEG	315°	COBHAM	AFS-DBG-0360-01	2' PANEL	1	REDLINE	RDL-3000	ODU	1	3/8"	INSIDE	F6	80'	STANDOFF	10'	2 3/8"	1' 6"
17	80'	A LEG	300°	RADIOWAVES	ILLEGIBLE	2' DISH	1	REDLINE	RDL-3000	ODU	1	3/8"	INSIDE	F6					
18	83'	A LEG	300°	RADIOWAVES	SPD2-5 2NS	2' DISH	1	REDLINE	RDL-3000	ODU	1	3/8"	INSIDE	F6					
19	83'	B LEG	15°	RADIOWAVES	HPCPE-23DW2	1' DISH	1	DRAGONWAVE	PHHP23B3SXR1	ODU	1	3/8"	INSIDE	F6	83'	STANDOFF	2'	2 7/8"	1' 6"
20	84'	A LEG	N/A	ILLEGIBLE	ILLEGIBLE	20' DIPOLE	NONE				1	7/8"	INSIDE	F8	84', 104'	STANDOFFS	2 3/8"	2 3/8"	6'
21	103'	C LEG	195°	RADIOWAVES	HPCPE-23DW2	1' DISH	1	DRAGONWAVE	PHHP23B3SXR1	ODU	1	3/8"	INSIDE	F6	103'	STANDOFF	2'	3 1/2"	1' 6"
22	111'	A LEG	N/A	ILLEGIBLE	ILLEGIBLE	20' OMNI	NONE				1	7/8"	INSIDE	F7	111'	STANDOFF	1'	2"	1' 6"
23	115' - 125'	B LEG	N/A	ILLEGIBLE	ILLEGIBLE	2 BAY FM: 2' T X 2' W X 2' L	NONE				1	7/8"	INSIDE	B LEG	115' - 125'	STANDOFF	1'	2"	1' 6"
24	131'	A LEG	275°	SCALA	ILLEGIBLE	PARAGRID: 18' T X 3' W	NONE				1	1/2"	INSIDE	F8	132'	PIPE MOUNT	2'	2 3/8"	6"
25	143'	A LEG	N/A	ILLEGIBLE	ILLEGIBLE	20' OMNI	NONE				1	7/8"	INSIDE	F8	142'	STANDOFF	2'	2 3/8"	4'
26	175' - 182'	C LEG	N/A	ILLEGIBLE	ILLEGIBLE	2 BAY FM: 3' T X 2' W X 2' L	NONE				1	1- 5/8"	INSIDE	F4	175'	PIPE MOUNT	20'	4 1/2"	1'
27	190'	A LEG	N/A	ILLEGIBLE	ILLEGIBLE	2' DIAMETER FM ELEMENT	NONE				1	7/8"	INSIDE	F7	190'	CLAMPSET TO LEG	N/A	N/A	N/A
28	198'	B LEG	N/A	ILLEGIBLE	ILLEGIBLE	15' OMNI	NONE				1	7/8"	INSIDE	F8	195'	STANDOFF	2'	2"	6'
29	218'	B LEG	N/A	ILLEGIBLE	ILLEGIBLE	6' OMNI	NONE				1	7/8"	INSIDE	F7	217'	STANDOFF	2'	2"	4'
30	219'	A LEG	N/A	ILLEGIBLE	ILLEGIBLE	4' OMNI	NONE				1	7/8"	INSIDE	F7	219'	CLAMPSET TO LEG	N/A	N/A	N/A
31	223'	B LEG	N/A	ILLEGIBLE	ILLEGIBLE	6' OMNI	1	ILLEGIBLE	ILLEGIBLE	10' X 12' X 8"	1	7/8"	INSIDE	F7	222'	PIPE MOUNT	4'	2 3/8"	6"

## Proventus Structural Services, LLC

Please contact Angie Shyrigh with any questions regarding the content of this report.  
(614)312-8107

## Observations

Elevation	Location	Description	Recommendation	Priority
78'	AB face	Dead feedlines (loading item #15) were observed to be installed.	It is recommended out of service or otherwise abandoned equipment be completely removed from the structure in order to reduce the resources required to maintain safe connection to the structure as well as to maintain accurate loading records.	To be scheduled
Varies	Varies	The stiff-arm associated with each antenna # 8, #9, #10, #11 is connected to a tower bracing member.	In order to prevent damage to the already structurally compromised bracing members it is recommended the stiff-arm connection be relocated to a tower leg.	To be scheduled

### Proventus Structural Services, LLC

Please contact Angie Shyrigh with any questions regarding the content of this report.  
(614)312-8107

## Guy Wires and Associated Hardware

Items inspected include:

- Strand condition (corrosion, breaks, nicks, kinks, etc.)
- Guy hardware conditions
  - Turnbuckles or equivalent (secure and safety properly applied)
  - Cable thimbles properly in place (if required)
  - Service sleeves properly in place (if required)
  - Cable connectors (end fittings)
    - Cable clamps applied and bolts tight
    - Wire serving properly applied
    - No signs of slippage or damaged strands
    - Preformed wraps – properly applied, fully wrapped and sleeves in place
    - Poured sockets secure and showing no separation
    - Shackles, bolts, pins and cotter pins secure and in good condition
- Guy tensions

*Note: 1) Minor variations in guy tensions are to be expected due to temperature and low wind speed conditions. The cause of significant changes should be determined immediately and proper remedial action taken. Possible cause may be initial construction loosening, previously experienced extreme wind or ice, anchor movements, base settlement, or connection slippage.*


*2) Tension variations at a single level are to be expected because of anchor elevation differences, construction deviations and wind effects.*

### **Proventus Structural Services, LLC**

*Please contact Angie Shyrigh with any questions regarding the content of this report.  
(614)312-8107*

## Guy Anchor and Guy Wire Position Codes

- The northernmost anchor is designated “A” followed by “B” and “C” clockwise.
- Outer anchors are designated with a double letter.
- Torque arm guy wires are labeled according to the anchor plate to which it is attached followed by the two paths the guy wire is between.



### Proventus Structural Services, LLC

Please contact Angie Shyrigh with any questions regarding the content of this report.  
(614)312-8107

## Guy Tension Results

Note: the ideal initial tension range is 7% under or 15% over the engineered tension. In the absence of engineered tensions, ideal initial tension is considered to be 10% of the manufacturer's rated breaking strength.

Temperature	77°
Wind Speed	12MPH
Wind Direction	W

Guy Wire Position Code	Anchor Distance	Anchor Elevation	Guy Wire Attachment Elevation	Guy Wire Diameter	Guy Wire Type	Ideal Initial Tension Range			Measured Tension	Result
						Low	Target	High		
A-CA	131'	+5'	70' 6"	1/2" X 7	EHS	2,455	2,640	3,036	2,400	9% UNDER TARGET TENSION
A-AB			70' 6"	1/2" X 7	EHS	2,455	2,640	3,036	3,300	25% OVER TARGET TENSION
A			140'	3/4" X 19	EHS	5,422	5,830	6,705	6,300	ACCEPTABLE TENSION
A-CA			205'	9/16" X 7	EHS	3,255	3,500	4,025	4,600	31% OVER TARGET TENSION
A-AB			205'	9/16" X 7	EHS	3,255	3,500	4,025	3,900	ACCEPTABLE TENSION
B-AB			135'	+2'	70' 6"	1/2" X 7	EHS	2,455	2,640	3,036
B-BC	70' 6"	1/2" X 7			EHS	2,455	2,640	3,036	3,100	17% OVER TARGET TENSION
B	140'	3/4" X 19			EHS	5,422	5,830	6,705	5,800	ACCEPTABLE TENSION
B-AB	205'	9/16" X 7			EHS	3,255	3,500	4,025	4,100	17% OVER TARGET TENSION
B-BC	205'	9/16" X 7			EHS	3,255	3,500	4,025	4,500	29% OVER TARGET TENSION
C-BC	135'	+15'			70' 6"	1/2" X 7	EHS	2,455	2,640	3,036
C-CA			70' 6"	1/2" X 7	EHS	2,455	2,640	3,036	3,000	ACCEPTABLE TENSION
C			140'	3/4" X 19	EHS	5,422	5,830	6,705	7,400	27% OVER TARGET TENSION
C-BC			205'	9/16" X 7	EHS	3,255	3,500	4,025	4,600	31% OVER TARGET TENSION
C-CA			205'	9/16" X 7	EHS	3,255	3,500	4,025	4,600	31% OVER TARGET TENSION

(4) of (15) guy wires are within the acceptable tension range.

(1) of (15) guy wires are under the acceptable tension range.

(10) of (15) guy wires are over the acceptable tension range.

It is recommended the guy wires be tensioned to bring them into the acceptable ranges.

### Proventus Structural Services, LLC

Please contact Angie Shyrigh with any questions regarding the content of this report.  
(614)312-8107



## Observations

Elevation	Location	Description	Recommendation	Priority
Ground	Anchor A	Scaling rust is present and advancing at the base of the Anchor A elevation beam.	It is recommended the Engineer of Record be consulted to determine corrective action.	To be scheduled within 12 months
Ground	Anchor B	Scaling rust is present at the guy anchor rods and approximately 1/4" material from the diameter of each anchor rod is present.	It is recommended the Engineer of Record be consulted to determine corrective action.	To be scheduled within 12 months
Ground	Each anchor	End sleeves are not present on the guy grip ends.	In order to protect the guy grip ends, it is recommended that end sleeves be installed. (6) 1/2" end sleeves, (3) 3/4" end sleeves and (6) 9/16" end sleeves are required to correct.	To be scheduled within 12 months
Ground	Anchor A	The level 2 guy wire ground has become detached.	Reattach the guy wire ground for proper lightning protection.	To be scheduled within 12 months
Ground	Anchor B	What appears to be electrical feed is draped over the top two guy wires and is secured and cushioned by what appears to be rubber foam.	It is strongly recommended that this feed be relocated away from the tower. The potential for serious injury, death, and equipment damage is great should either the tower or the feed fails.	To be scheduled within 3 months

### Proventus Structural Services, LLC


Please contact Angie Shyrigh for any questions regarding the content of this report.  
 (614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)

# Tower Alignment

The tower twist and plumb are within acceptable limits.

Temperature	77°
Wind Speed	12MPH
Wind Direction	W

Mast Elevation in FT.	OBSERVED MAST DATA				CALCULATED TWIST			CALCULATED OUT-OF-PLUMB		
	A IN.	D1 IN.	D2 IN.	D3 IN.	d IN.	e	a DEG.	x IN.	y IN.	r IN.
0.00	42.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
70.00	42.00	-0.40	0.10	-0.20	-0.17	-0.01	-0.39	0.17	-0.23	0.29
140.00	42.00	-0.40	-0.50	-0.60	-0.50	-0.02	-1.18	0.06	0.10	0.12
205.00	42.00	-1.70	-0.60	-1.30	-1.20	-0.05	-2.84	0.40	-0.50	0.64



## Proventus Structural Services, LLC

Please contact Angie Shyrigh for any questions regarding the content of this report.  
 (614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)

# Photos



Tower signage  
File 001



Tower profile  
File 002




Base of tower  
File 003



A Leg  
File 004

## Proventus Structural Services, LLC

Please contact Angie Shyrigh for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)



AB Face  
File 005



Base of tower  
File 006



B Leg  
File 007



BC Face  
File 008

**Proventus Structural Services, LLC**

Please contact *Angie Shyrigh* for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)





Base of tower  
File 009



C Leg  
File 010



CA Face  
File 011



Anchor A  
File 012

**Proventus Structural Services, LLC**

Please contact *Angie Shyrigh* for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)



Anchor A  
File 013



Anchor A  
File 014



Anchor A  
File 015



Tower profile  
File 016

**Proventus Structural Services, LLC**  
Please contact *Angie Shyrigh* for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)



Tower profile  
File 017



Tower profile  
File 018



Tower profile  
File 019



Tower profile  
File 020

**Proventus Structural Services, LLC**

Please contact *Angie Shyrigh* for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)





Anchor B  
File 021



Anchor B  
File 022



Anchor B  
File 023



Anchor B  
File 024

**Proventus Structural Services, LLC**

Please contact *Angie Shyrigh* for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)





Anchor B  
File 025



Tower profile  
File 026



Tower profile  
File 027



Tower profile  
File 028

**Proventus Structural Services, LLC**

Please contact *Angie Shyrigh* for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)



Tower profile  
File 029



Tower profile  
File 030



Anchor C  
File 031



Anchor C  
File 032

**Proventus Structural Services, LLC**

Please contact *Angie Shyrigh* for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)





Anchor C  
File 033



Anchor C  
File 034



Tower profile  
File 035



Tower profile  
File 036

**Proventus Structural Services, LLC**

Please contact *Angie Shyrigh* for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)



Tower profile  
File 037



Tower profile  
File 038



Tower profile  
File 039



Base of tower  
File 040

**Proventus Structural Services, LLC**

Please contact *Angie Shyrigh* for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)





Base plate  
File 041



Base plate  
File 042



Base plate  
File 043



5' leg splice  
File 044

**Proventus Structural Services, LLC**

Please contact *Angie Shyrigh* for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)



30' leg splice  
File 045



20' - 40' section  
File 046



Hardware condition  
File 047



Safety cable condition  
File 048

**Proventus Structural Services, LLC**

Please contact *Angie Shyrigh* for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)





Antenna #1  
File 049



Tower surface condition  
File 050



Hardware condition  
File 051



Hardware condition  
File 052

**Proventus Structural Services, LLC**

Please contact Angie Shyrigh for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)



Hardware condition  
File 053



40' leg splice  
File 054



40' - 60' section  
File 055



Tower surface condition  
File 056

**Proventus Structural Services, LLC**

Please contact Angie Shyrigh for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)





Tower surface condition  
File 057



Tower surface condition  
File 058



Tower surface condition  
File 059



Tower surface condition  
File 060

**Proventus Structural Services, LLC**

Please contact *Angie Shyrigh* for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)



Tower surface condition  
File 061



Antenna #2  
File 062



Antenna #3  
File 063



Antenna #5  
File 064

**Proventus Structural Services, LLC**

Please contact Angie Shyrigh for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)



Antenna #4  
File 065



Antenna #4 label  
File 066



Antennas #6, #7  
File 067



Tower surface condition  
File 068

**Proventus Structural Services, LLC**

Please contact Angie Shyrigh for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)





Antennas #8, #10  
File 069



Antennas #9, #11  
File 070



Stiff arm connections  
File 071



60' leg splice  
File 072

**Proventus Structural Services, LLC**

Please contact *Angie Shyrigh* for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)



60' - 80' section  
File 073



Antenna #10  
File 074



Antenna #10 stiff arm connection  
File 075



Antenna #11  
File 076

**Proventus Structural Services, LLC**

Please contact *Angie Shyrigh* for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)





Antenna #10 stiff arm connection to damaged diagonal  
File 077



Antenna #10 stiff arm connection to damaged diagonal  
File 078



Tower surface condition  
File 079



Tower surface condition  
File 080

**Proventus Structural Services, LLC**

Please contact Angie Shyrigh for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)



Tower surface condition  
File 081



Tower surface condition  
File 082



Tower surface condition  
File 083



Tower surface condition  
File 084

**Proventus Structural Services, LLC**

Please contact *Angie Shyrigh* for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)





Torque arm  
File 085



Torque arm  
File 086



Torque arm  
File 087



Torque arm  
File 088

**Proventus Structural Services, LLC**

Please contact *Angie Shyrigh* for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)





Guy path B  
File 089



Guy path C  
File 090



Antenna #12  
File 091



Antennas #12, #13, #14  
File 092

**Proventus Structural Services, LLC**

Please contact Angie Shyrigh for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)



Antennas #16, #17, #18  
File 093



Antennas #16, #17, #18, #20  
File 094



Tower surface condition  
File 095



Tower surface condition  
File 096

**Proventus Structural Services, LLC**

Please contact *Angie Shyrigh* for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)





Tower surface condition  
File 097



Antenna #20  
File 098



Antenna #19  
File 099



Tower surface condition  
File 100

**Proventus Structural Services, LLC**

Please contact *Angie Shyrigh* for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)



Tower surface condition  
File 101



Tower surface condition  
File 102



Dead feedlines  
File 103



80' leg splice  
File 104

**Proventus Structural Services, LLC**


Please contact *Angie Shyrigh* for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)



80' - 100' section  
File 105



Tower surface condition  
File 106



Tower surface condition  
File 107



Tower surface condition  
File 108

**Proventus Structural Services, LLC**

Please contact *Angie Shyrigh* for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)





100' leg splice  
File 109



100' - 120' section  
File 110



Antenna #21  
File 111



Tower surface condition  
File 112

**Proventus Structural Services, LLC**

Please contact Angie Shyrigh for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)



Tower surface condition  
File 113



Tower surface condition  
File 114



Tower surface condition  
File 115



Tower surface condition  
File 116

**Proventus Structural Services, LLC**

Please contact *Angie Shyrigh* for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)





Tower surface condition  
File 117



Tower surface condition  
File 118



Tower surface condition  
File 119



Tower surface condition  
File 120


**Proventus Structural Services, LLC**

Please contact *Angie Shyrigh* for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)





Tower surface condition  
File 121



Tower surface condition  
File 122



Tower surface condition  
File 123



Tower surface condition  
File 124

**Proventus Structural Services, LLC**

Please contact *Angie Shyrigh* for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)



Torque arm hardware  
File 125



Torque arm hardware  
File 126



Guy attachment  
File 127



Guy attachment  
File 128

**Proventus Structural Services, LLC**

Please contact *Angie Shyrigh* for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)



Tower surface condition  
File 129

**Proventus Structural Services, LLC**

*Please contact Angie Shyrigh for any questions regarding the content of this report.  
(614) 312-8107 or [angie@proventusonline.com](mailto:angie@proventusonline.com)*