



*Figure 1 - Intrusive investigation into dry-stone wall*



*Figure 2 - Further view of investigation. No sound rock was found, only fill material and dry stack.*



*Figure 3 - Close up view of investigation. Only fill material found.*